CESSNA 170/172/175

ELEVATORS & STABILIZERS

Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original high impact plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired with readily available fiberglass repair kits from your local automotive parts store.



Description	Part No.	Price
172 Horizontal Tip 1963 & on (SA-0532001-93)	05-03744	
172/175 Horizontal Tip Straight Tail (SA-0532001-61)	05-03743	
172 Elevator Tip 1963 & on LH (SA-0532001-94)	05-03742	
172 Elevator Tip 1963 & on RH (SA-0532001-100)	05-03741	
172/175 Elevator Tip Straight Tail (SA-0532001-62)	05-03740	

STRUT CUFFS

Here's an unbeatable item for renovating your Cessna; a set of replacement strut cuffs. Order just one cuff to replace a damaged original, or get a set of four for a complete replacement.



Description	Part No.	Price
172 Strut Cuff Upper 1973 & on RH (SA-0523047-2)	05-03739	
172 Strut Cuff Upper 1973 & on LH (SA-0523047-1)	05-03738	
172 Strut Cuff Lower (all models) RH (SA-0522150-2)	05-03736	
172 Strut Cuff Lower (all models) LH (SA-0522150-1)	05-03735	

WING & DORSAL TIPS

Wing tips are a common victim of hanger and ramp rash. Maybe you thought the plane was going to clear those doors as you wheeled it back into the hanger...the first indication that you were wrong was that grating sound as the wing tip met metal. Here's the solution: replacement fiberglass wing tips from Stene Aviation.



Description	Part No.	Price
172 Wing Tip (small droop) 1968-'72 LH (SA-0523565-29)	05-03726	
172 Wing Tip (small droop) 1968-'72 RH (SA-0523565-30)	05-03727	
172 Wing Tip (small droop) 1973&on LH (SA-0723200-5)	05-03762	
172 Wing Tip (small droop) 1973&on RH (SA-0723200-6)	05-03764	
172 Mid-Dorsal (SA-0531012-2)	05-03759	
172 Dorsal Tip 1972&on (SA-0531020-1)	05-03760	
Cable Covers (SA-0530011-2)	05-03770	

RUDDER & VERTICAL FIN CAPS

These parts are a snap to replace on most planes. Please note, indicate if you have a straight tail or a swept tail. It is also important to let us know if your fin cap needs to accommodate a strobe or beacon, and if so, if the light is front-mounted or center-mounted.



Part No.	Price
05-03745	
05-03746	
05-03747	
05-03752	
05-03748	
05-03749	
05-03753	
05-03754	
05-03750	
05-03751	
05-03756	
05-03755	
05-03757	
05-12809	
05-12810	
	05-03745 05-03746 05-03747 05-03752 05-03748 05-03753 05-03754 05-03750 05-03756 05-03755 05-03757 05-03757

GEAR LEG AND BRAKE FAIRINGS

These are excellent items for replacing worn plastic originals. Your fiberglass replacements will be more durable with an improved finish over the original plastics.



Description	Part No.	Price
172 Upper Gear Leg 1971&on RH (SA-1741005-240)	05-03767	
172 Upper Gear Leg 1971&on LH (SA-1741005-239)	05-03766	
172 Brake Fairing 1974& on LH (SA-0541224-1)	05-03768	
172 Brake Fairing 1974&on RH (SA-0541224-2)	05-03769	
172 Upper Gear Leg Fairing LH 172R, 172S (SA-1741005-59)	05-12872	
172 Upper Gear Leg Fairing RH 172R, 172S (SA-1741005-60)	05-12873	

WHEEL PANTS

Replace your original plastic wheel pants with high quality and durable fiberglass replacements. All wheel pants come with a 2" access plug for checking tire pressure. Original hardware is required for mounting.



172 Wheel Pant 1974&on LH (SA-0541223-17)

172 Nose Wheel Pant 1974 & on (SA-0543079-3) 05-03730

SEE WWW.AIRCRAFTSPRUCE.COM FOR COMPLETE LISTING

05-03729