

AVIATION MAINTENANCE TECHNICIAN CERTIFICATION SERIES

MAINTENANCE PRACTICES

7



EASA 2023-889 COMPLIANT

Update notices for this book will be available online at www.actechbooks.com/revisions.html
If you would like to be notified when changes occur, please join our mailing list at www.actechbooks.com

VERSION	EFFECTIVE DATE	DESCRIPTION OF REVISION(S)
001	2020.02	Module creation and release.
001.1	2021.10	Corrected description of file types (Submodule 7, pages 3.15-3.16).
001.2	2023.04	Submodule 8 - Added content on Friction and Mechanical lock blind rivet procedures. Inclusion of Measurement Standards for clarification, page iv. Minor appearance and format updates.
002	2024.04	Regulatory update for EASA 2023-989 Compliance.
002.1	2025.01	Page 5.8 - Corrected orientation of Figure 5-10B. Page 12.3 - Corrected orientation of checknuts Figure 12-9.

Module was reorganized based upon the EASA 2023-989 subject criteria. Enhancements included in this version 002.1 are:

- 7.1 *Fuel Tank Safety* - topic added.
- 7.1 *Ballistic Parachutes* - topic added.
- 7.4 *Avionics Test Equipment* - topic moved to Modules 11, 12, and 13 per 2023-989.
- 7.7 *Connector Pin Wire Support* - topic added.
- 7.7 *Soldering Electrical Wires* - topic added.
- 7.7 *HIRF Protection Principles* - topic added.
- 7.8 *Special Purpose Rivets and Fasteners* - topic added.
- 7.9 *Visual Inspection of Springs* - topic added.
- 7.9 *Inspecting Squareness of Springs* - topic added.
- 7.13 *Cable Tension Regulators* - topic added.
- 7.13 *Cable Guides and Adjustment* - topic added.
- 7.14 *Additive Manufacturing* - topic added.
- 7.15 *Welding* - submodule deleted per 2023-989.
- 7.18 *Structural Repair Manuals* - topic added.
- 7.18 *Dye Penetrant Color Contrast* - topic added.
- 7.19 *HIRF Test Equipment* - topic added.
- 7.21 *Documentation and Communication* - new submodule added.

MEASUREMENT STANDARDS

SI Units

The measurements used in this book are presented with the International System of Units (SI) standards in all cases except when otherwise specified by ICAO (for example, altitude expressed in feet or performance numbers as specified by a manufacturer). The chart below can be used should your studies call for conversions into imperial numbers.

Number Groups

This book uses the International Civil Aviation Organization (ICAO) standard of writing numbers. This method separates groups of 3 digits with a space, versus the European method by periods and the American method by commas.

For example, the number one million is expressed as:

ICAO Standard	1 000 000
European Standard	1.000.000
American Standard	1,000,000

Prefixes

The prefixes used in the table below form names of the decimal equivalents in SI units.

PREFIX AND SYMBOLS CHART

MULTIPLICATION FACTORS	PREFIX	SYMBOL
1 000 000 000 000 000 000 = 10^{18}	exa	E
1 000 000 000 000 000 = 10^{15}	peta	P
1 000 000 000 000 = 10^{12}	tera	T
1 000 000 000 = 10^9	giga	G
1 000 000 = 10^6	mega	M
1 000 = 10^3	kilo	k
100 = 10^2	hecto	h
10 = 10^1	deca	da
0.1 = 10^{-1}	deci	d
0.01 = 10^{-2}	centi	c
0.001 = 10^{-3}	milli	m
0.000 001 = 10^{-6}	micro	μ
0.000 000 001 = 10^{-9}	nano	n
0.000 000 000 001 = 10^{-12}	pico	p
0.000 000 000 000 001 = 10^{-15}	femto	f
0.000 000 000 000 000 001 = 10^{-18}	atto	a

COMMON CONVERSIONS CHART

IMPERIAL	TO	SI (METRIC)
Distance		
1 Inch	is equal to	2.54 Centimeters
1 Foot	is equal to	0.304 Meters
1 (Statute) Mile	is equal to	1.609 Kilometers
Weight		
1 Pound	is equal to	0.454 Kilograms
Volume		
1 Quart	is equal to	0.946 Liters
1 Gallon	is equal to	3.785 Liters
Temperature		
$^{\circ}$ Fahrenheit	is equal to	(-) 17.778° Celsius ($^{\circ}$ C)
$^{\circ}$ Fahrenheit	is equal to	255.37 Kelvin (K)
Area		
1 Square Inch	is equal to	6.451 Square Centimeters
1 Square Foot	is equal to	0.093 Square Meters
1 Square Mile	is equal to	2.59 Square Kilometers
Velocity		
1 Foot Per Second	is equal to	0.304 Meters Per Second
1 Mile Per Hour	is equal to	1.609 Kilometers Per Hour
1 Knot	is equal to	1.852 Kilometers Per Hour

SI (METRIC)	TO	IMPERIAL
Distance		
1 Centimeter	is equal to	0.394 Inches
1 Meter	is equal to	3.28 Feet
1 Kilometer	is equal to	0.621 Miles
Weight		
1 Kilogram	is equal to	2.204 Pounds
Volume		
1 Liter	is equal to	1.057 Quarts
1 Liter	is equal to	0.264 Gallons
Temperature		
$^{\circ}$ Celsius ($^{\circ}$ C)	is equal to	33.8° Fahrenheit
$^{\circ}$ Kelvin (K)	is equal to	(-) 437.87° Fahrenheit
Area		
1 Square Centimeter	is equal to	0.155 Square Inches
1 Square Meter	is equal to	10.764 Square Feet
1 Square Kilometer	is equal to	0.386 Square Miles
Velocity		
1 Meter Per Second	is equal to	3.281 Feet Per Second
1 Kilometer Per Hour	is equal to	0.621 Miles Per Hour
1 Kilometer Per Hour	is equal to	0.540 Knots

Pressure

pounds per square inch (psi)	kiloPascals (kPa)	6.897
pounds per square inch (psi)	Pascals (Pa)	6.894

BASIC KNOWLEDGE REQUIREMENTS

Qualification on basic subjects for each aircraft maintenance license category or subcategory is accomplished in accordance with the following matrix. Where applicable, subjects are indicated by an "X" in the column below the license heading.

EASA LICENSE CATEGORY CHART MODULE NUMBER AND TITLE		A1 Airplane Turbine	B1.1 Airplane Turbine	B1.2 Airplane Piston	B1.3 Helicopter Turbine	B1.4 Helicopter Piston	B2 Avionics
1	Mathematics	X	X	X	X	X	X
2	Physics	X	X	X	X	X	X
3	Electrical Fundamentals	X	X	X	X	X	X
4	Electronic Fundamentals		X	X	X	X	X
5	Digital Techniques, Electronic Instrument Systems	X	X	X	X	X	X
6	Materials and Hardware	X	X	X	X	X	X
7	Maintenance Practices	X	X	X	X	X	X
8	Basic Aerodynamics	X	X	X	X	X	X
9	Human Factors	X	X	X	X	X	X
10	Aviation Legislation	X	X	X	X	X	X
11	Aeroplane Aerodynamics, Structures and Systems	X	X				
12	Rotorcraft Aerodynamics, Structures and Systems				X	X	
13	Aircraft Aerodynamics, Structures and Systems						X
14	Propulsion						X
15	Gas Turbine Engine	X	X		X		
16	Piston Engine			X		X	
17	Propeller	X	X	X			

Basic knowledge requirements as outlined in Part-66, Appendix I

The knowledge level indicators are defined on 3 levels as follows:

Level 1

A familiarization with the principal elements of the subject.

Objectives:

- The applicant should be familiar with the basic elements of the subject.
- The applicant should be able to give a simple description of the whole subject, using common words and examples.
- The applicant should be able to use typical terms.

Level 2

A general knowledge of the theoretical and practical aspects of the subject and an ability to apply that knowledge.

Objectives:

- The applicant should be able to understand the theoretical fundamentals of the subject.
- The applicant should be able to give a general description of the subject using, as appropriate, typical examples.
- The applicant should be able to use mathematical formula in conjunction with physical laws describing the subject.
- The applicant should be able to read and understand sketches, drawings and schematics describing the subject.
- The applicant should be able to apply his knowledge in a practical manner using detailed procedures.

Level 3

A detailed knowledge of the theoretical and practical aspects of the subject and a capacity to combine and apply the separate elements of knowledge in a logical and comprehensive manner.

Objectives:

- The applicant should know the theory of the subject and interrelationships with other subjects.
- The applicant should be able to give a detailed description of the subject using theoretical fundamentals and specific examples.
- The applicant should understand and be able to use mathematical formula related to the subject.
- The applicant should be able to read, understand and prepare sketches, simple drawings and schematics describing the subject.
- The applicant should be able to apply his knowledge in a practical manner using manufacturer's instructions.
- The applicant should be able to interpret results from various sources and measurements and apply corrective action where appropriate.

PART 66 BASIC KNOWLEDGE REQUIREMENTS

SUBMODULE KNOWLEDGE DESCRIPTIONS		LEVEL
		A
7.1	Safety Precautions – Aircraft and Workshop Aspects of safe working practices including precautions to be taken when working with electricity, gases (especially oxygen), oils, and chemicals. Fuel tank safety, fuel tank entry procedures and precautions. Awareness and precautions regarding aircraft equipped with ballistic recovery systems. Also, instructions in the remedial action to be taken in the event of a fire or another accident with one or more of these hazards including knowledge of fire extinguishing agents.	3
7.2	Workshop Practices Care of tools / drills and reamers, control of tools, use of workshop materials; Dimensions, allowances and tolerances, workmanship standards; Calibration of tools and equipment, calibration standards.	3
7.3	Tools Common hand-tool types; Common power-tool types; Operation and use of precision-measuring tools; Lubrication equipment and methods; Operation, function, and use of electrical general test equipment.	3
7.4	Submodule reserved for future use.	–
7.5	Engineering Drawings, Diagrams, and Standards Drawing types and diagrams, their symbols, dimensions, tolerances and projections; Identification of title block information; Microfilm, microfiche, and computerised presentations; Specification 100 of the Air Transport Association (ATA) of America; Aeronautical and other applicable standards including ISO, AN, MS, NAS and MIL; Wiring diagrams and schematic diagrams.	1
7.6	Fits and Clearances Drill sizes for bolt holes, classes of fits; Common system for fits and clearances; Schedule of fits and clearances for aircraft and engines; Limits for bow, twist and wear; Standard methods for checking shafts, bearings, and other parts.	1
7.7	Electrical Wiring Interconnection System (EWIS) Continuity, insulation and bonding techniques and testing; Use of crimp tools: hand and hydraulic operated; Testing of crimp joints; Connector pin removal and insertion; Coaxial cables: testing and installation precautions; Identification of wire types, their inspection criteria and damage tolerance; Wiring protection techniques: cable looming and loom support, cable clamps, protective sleeving techniques including heat shrink wrapping, shielding; High-Intensity Radiated Fields (HIRF) and protection principles; Soldering of electrical wires, EWIS installations, inspection, repair, maintenance, and cleanliness standards.	1
7.8	Riveting Riveted joints, rivet spacing and pitch; Tools used for riveting and dimpling; Inspection of riveted joints.	1
7.9	Pipes and Hoses Bending and belling/flaring aircraft pipes; Inspection and testing of aircraft pipes and hoses; Installation and clamping of pipes.	1
7.10	Springs Inspection and testing of springs.	1
7.11	Bearings Testing, cleaning and inspection of bearings; Lubrication requirements for bearings; Defects in bearings and their causes.	1
7.12	Transmissions Inspection of gears, backlash; Inspection of belts and pulleys, chains and sprockets; Inspection of screw jacks, lever devices, push–pull rod systems.	1

PART 66 BASIC KNOWLEDGE REQUIREMENTS

SUBMODULE KNOWLEDGE DESCRIPTIONS		LEVEL
		A
7.13	Control Cables Swaging of end fittings; Inspection and testing of control cables; Bowden cables; aircraft flexible control systems.	1
7.14	Material Handling 7.14.1 Sheet Metal Marking out and calculation of bend allowance; Sheet metal working, including bending and forming; Inspection of sheet metal work.	-
7.14.2	Composite and Non-metallic Bonding practices; Environmental conditions; Inspection methods.	-
7.14.3	Additive Manufacturing Common additive manufacturing techniques and their influence on the mechanical properties of the finished part; Inspection of additive manufactured parts and common production failures.	1
7.15	Submodule reserved for future use.	–
7.16	Aircraft Weight and Balance (a) Calculation of centre-of-gravity / balance limits: use of relevant documents. (b) Preparation of aircraft for weighing; Aircraft weighing.	- -
7.17	Aircraft Handling and Storage Aircraft taxiing/towing and associated safety precautions; Aircraft jacking, chocking, securing and associated safety precautions; Aircraft storage methods; Refuelling/defuelling procedures; De-icing/anti-icing procedures; Electrical, hydraulic, and pneumatic ground supplies; Effects of environmental conditions on aircraft handling and operation.	2
7.18	Disassembly, Inspection, Repair, and Assembly Techniques (a) Types of defects and visual inspection techniques; Corrosion removal, assessment and reprotection; (b) General repair methods, structural repair manual; Ageing, fatigue, and corrosion control programmes; (c) Non-destructive inspection techniques including penetrant, radiographic, eddy current, magnetic particle, ultrasonic and borescope inspections; including practical training in colour contrast penetrant inspection; (d) Disassembly and reassembly techniques; (e) Troubleshooting techniques.	2 - - 2 -
7.19	Abnormal Events (a) Inspections following lightning strikes and HIRF penetration; (b) Inspections following abnormal events such as heavy landings and flight through turbulence.	2 2
7.20	Maintenance Procedures Maintenance planning; Modification procedures; Stores procedures; Certification/release procedures; Interface with aircraft operation; Maintenance Inspection / Quality Control / Quality Assurance; Additional maintenance procedures; Control of life-limited components.	1
7.21	Documentation and Communication Documentation: elements and criteria for writing work reports, troubleshooting reports, and shift handover instructions. Communication: clear, comprehensive, and concise.	1

TABLE OF CONTENTS

MAINTENANCE PRACTICES

Revision Log	iii
Measurement Standards	iv
Basic Knowledge Requirements	v
Part 66 Basic Knowledge Requirements	vi
Table of Contents	ix

7.1 - SAFETY PRECAUTIONS — AIRCRAFT AND WORKSHOP 1.1

Safety Around Electricity	1.1
Fire Safety Around Electricity	1.1
Safety Around Compressed Gases	1.2
Oxygen Safety Considerations	1.2
Safety Around Hazardous Materials	1.2
Safety Around Machine Tools	1.3
Fuel Tank Entry Procedures and Precautions	1.4
Fuel Tank Entry Procedures and Precautions	1.4
Chemical Hazards	1.4
Physical Hazards	1.4
Preparation for Entry	1.5
Ensuring Adequate Ventilation	1.5
Ventilation Techniques	1.5
Monitoring Air in Fuel Tanks	1.5
Conditions Required for Entry	1.5
Communication	1.5
Respiratory Protection	1.5
Electrically Powered Equipment	1.5
Airplane Damage Considerations	1.6
Ballistic Recovery Systems	1.6
Awareness and Precautions Regarding Ballistic Recovery Systems	1.6
Basic Understanding	1.6
Primary Components	1.6
Safety Around Ballistic Recovery Systems	1.6
Inspection and Maintenance	1.6
Installation and Removal	1.7
Fire Safety	1.7
Requirements for a Fire to Occur	1.7
Classification of Fires	1.7
Ordinary Combustibles	1.7
Flammable Liquid and Gas	1.8
Electrical	1.8
Metal	1.8
Cooking Oils	1.8
European Standards	1.8
Fire Extinguishers	1.9
Identifying Fire Extinguishers	1.11
Inspection of Fire Extinguishers	1.11
Using Fire Extinguishers	1.12
Flight Line Safety	1.12
Hearing Protection	1.12
Foreign Object Damage (FOD)	1.12
Safety Around Airplanes	1.12
Safety Around Helicopters	1.12
Submodule 1 Practice Questions	1.13
Submodule 1 Practice Answers	1.14

7.2 - WORKSHOP PRACTICES.....2.1

Care and Control of Tools; Use of Workshop Materials	2.1
Care of Tools	2.1
Benches	2.1
Vices	2.1
Drilling Machines	2.1
Grinder	2.1
Motor Drives	2.2
Measuring Instruments	2.2
Drills and Reamers	2.2
Control of Tools	2.2
Tool Control Procedures	2.2
Workshop Materials	2.3
Dimensions, Allowances and Tolerances; Workmanship Standards	2.3
Dimensions, Allowances, and Tolerances	2.3
Standards of Workmanship	2.4
Tool Calibration	2.4
Submodule 2 Practice Questions	2.7
Submodule 2 Practice Answers	2.8

7.3 - TOOLS.....3.1

Common Hand Tools	3.1
Screwdrivers	3.1
Pliers and Plier-Type Cutting Tools	3.2
Clamps and Vises	3.3
C-Clamps	3.3
Vises	3.3
Hammers and Mallets	3.3
Punches	3.4
Wrenches	3.4
Open-End Wrenches	3.5
Box-End Wrenches	3.5
Socket Wrenches	3.5
Adjustable Wrenches	3.5
Special Wrenches	3.5
Strap Wrenches	3.6
Impact Wrenches	3.7
Torque Wrenches	3.7
Torque Tables	3.8
Cutting Tools	3.8
Hand Snips	3.9
Metal Shears	3.10
Hacksaws	3.10
Chisels	3.10
Files	3.11
File Types and Use	3.12
Commonly Used Files	3.12
Care of Files	3.13
Burring Tools	3.13
Reamers	3.13
Taps and Dies	3.14
Common Power Tools	3.16
Saws	3.16
Circular Cutting Saws	3.16
Kett Saw	3.16

TABLE OF CONTENTS

Pneumatic Circular-Cutting Saw	3.16	Twist Drill Bits	3.29
Reciprocating Saw	3.16	Cobalt Alloy Drill Bits	3.29
Die Grinders	3.17	Step Drill Bits	3.29
Cut-Off Wheels	3.17	Twist Drill Construction and Sizes	3.29
Nibblers	3.17	Drill Bit Sizes	3.30
Table Top, and Bench Tools	3.17	Hole Drilling Techniques	3.31
Notchers	3.17	Drilling Large Holes	3.34
Band Saws	3.17	Drill Lubrication	3.34
Metal Shears	3.18	Drill Accessories	3.34
Throatless Shears	3.18	Drill Stops	3.34
Scroll Shears	3.18	Drill Bushings	3.34
Rotary Punch Press	3.18	Drill Bushing Holder	3.34
Foot Operated Shears	3.18	Precision Measuring Tools	3.35
Squaring Shears	3.18	Rules	3.35
Sanders	3.19	Combination Sets	3.35
Disk Sander	3.19	Scriber	3.35
Belt Sander	3.19	Dividers and Pencil Compasses	3.35
Grinders	3.19	Calipers	3.36
Grinding Wheels	3.20	Micrometer Calipers	3.37
Bending Tools	3.20	Micrometer Parts	3.37
Bar Folding Machine	3.21	Reading a Micrometer	3.37
Cornice Brake	3.21	Vernier Scale	3.38
Box and Pan Brake	3.21	Using a Micrometer	3.38
Press Brake	3.22	Dial Indicator	3.39
Slip Roll Former	3.22	Slide Calipers	3.39
Rotary Machine	3.23	Lubrication Equipment	3.39
Shrinking, Stretching Tools and Procedures	3.23	Electrical Test Equipment	3.40
Shrinking Tools	3.23	DC Measuring Equipment	3.40
Stretching Tools	3.24	D'Arsonval Meter Movement	3.40
Forming Tools and Procedures	3.24	Current Sensitivity and Resistance	3.41
Stretch Forming	3.24	Dampening	3.41
Drop Hammer	3.24	Electrical Damping	3.41
Hydropress Forming	3.24	Mechanical Damping	3.41
Spin Forming	3.24	Multirange Ammeter	3.42
Forming with an English Wheel	3.25	Precautions	3.42
Piccolo Former	3.25	Voltmeters	3.42
Manual Sheet Metal Shrinker	3.25	Voltmeter Sensitivity	3.42
Hand-Operated Shrinker/Stretcher	3.26	MultiRange Voltmeters	3.42
Forming Blocks	3.26	Voltmeter Circuit Connections	3.43
Dollies and Stakes	3.26	Influence of the Voltmeter in the Circuit	3.43
Hardwood Form Blocks	3.26	Ohmmeter	3.43
V-Blocks	3.26	Zero Adjustment	3.43
Shrinking Blocks	3.26	Ohmmeter Scale	3.43
Sandbags	3.26	Multirange Ohmmeter	3.44
Hammers and Mallets	3.26	Megger (Megohmmeter)	3.44
Drilling	3.26	AC Measuring Equipment	3.45
Portable Power Drills	3.27	Electrodynamometer Meter Movement	3.46
Pneumatic Drill Motors	3.27	Moving Iron Vane Meter	3.46
Angled Drill Motors	3.27	Inclined Coil Iron Vane Meter	3.47
Two Hole Drill Motors	3.27	Varmeters	3.47
Drill Extension and Adapters	3.27	Wattmeter	3.47
Extension Drill Bits	3.27	Oscilloscope	3.47
Angle Adapters	3.28	Horizontal Deflection	3.48
Snake Attachment	3.28	Vertical Deflection	3.49
Drill Press	3.28	Tracing a Sine Wave	3.49
Types of Drill Bits	3.28	Control Features on an Oscilloscope	3.49

TABLE OF CONTENTS

Flat Panel Color Displays for Oscilloscopes	3.50	Detail View	5.9
Digital Multimeters	3.50	Pictorial Drawings	5.10
Basic Circuit Analysis and Troubleshooting	3.51	Perspective Drawings	5.10
Voltage Measurement	3.51	Isometric Drawings	5.10
Current Measurement	3.51	Oblique Drawings	5.10
Checking Resistance	3.52	Exploded View Drawings	5.10
Continuity Checks	3.52	Lines and Their Meanings	5.10
Capacitance Measurement	3.52	Centerlines	5.10
Inductance Measurement	3.53	Dimension Lines	5.10
Troubleshooting the Open Faults in Series Circuits	3.53	Extension Lines	5.11
Tracing Opens with the Voltmeter	3.54	Sectioning Lines	5.12
Tracing Opens with the Ohmmeter	3.54	Phantom Lines	5.12
Troubleshooting the Shorting Faults in Series Circuits	3.54	Break Lines	5.12
Tracing Shorts with the Ohmmeter	3.55	Leader Lines	5.12
Tracing Shorts with the Voltmeter	3.55	Hidden Lines	5.12
Troubleshooting the Open Faults in Parallel Circuits	3.55	Outline or Visible Lines	5.12
Tracing an Open with an Ammeter	3.56	Stitch Lines	5.12
Tracing an Open with an Ohmmeter	3.56	Cutting Plane and Viewing Plane Lines	5.12
Troubleshooting the Shorting Faults in Parallel Circuits	3.56	Drawing Symbols	5.12
Troubleshooting the Shorting Faults in Series-Parallel Circuits	3.56	Material Symbols	5.13
Tracing Opens with the Voltmeter	3.57	Shape Symbols	5.13
Submodule 3 Practice Questions	3.59	Electrical Symbols	5.13
Submodule 3 Practice Answers	3.60	Care of Drafting Tools	5.13
Submodule 3 Practice Questions	3.61	Title Blocks	5.13
Submodule 3 Practice Answers	3.62	Drawing or Print Numbers	5.13
7.4 - RESERVED	4.1	Reference and Dash Numbers	5.13
This submodule is reserved by EASA for future use.	4.1	Computerized Presentations	5.14
7.5 - ENGINEERING DRAWINGS, DIAGRAMS, AND STANDARDS 5.1		Microfilm and Microfiche	5.14
Purpose and Function of Aircraft Drawings	5.1	Digital Images	5.14
Drawings and Diagrams; Symbols, Dimensions, Tolerances, and Projections	5.1	Specification 100 of the Air Transport Association (ATA) ...	5.16
Drawing Types	5.1	ATA 100 and iSpec 2200	5.16
Detail Drawings	5.1	Aeronautical Standards	5.17
Assembly Drawings	5.2	ISO	5.17
Installation Drawings	5.2	AN (Army/Navy)	5.18
Sectional View Drawings	5.2	MS (Military Standard)	5.18
Full Section	5.2	NAS (National Aerospace Standard)	5.18
Half Section	5.2	BS (British Standards)	5.18
Revolved Section	5.2	Wiring and Schematic Diagrams	5.18
Removed Section	5.2	Diagrams	5.18
Drawing Standards	5.2	Installation Diagrams	5.18
Bill of Material	5.2	Schematic Diagrams	5.18
Other Drawing Data	5.2	Block Diagrams	5.18
Revision Block	5.2	Wiring Diagrams (Schematics)	5.18
Notes	5.2	Flowcharts	5.18
Zone Numbers	5.2	Troubleshooting Flowchart	5.18
Station Numbers and Location Identification on Aircraft ...	5.2	Logic Flowchart	5.18
Allowances and Tolerances	5.6	Submodule 5 Practice Questions	5.23
Finish Marks	5.8	Submodule 5 Practice Answers	5.24
Scale	5.8	7.6 - FITS AND CLEARANCES	6.1
Methods of Illustration	5.8	Drill Sizes for Bolt Holes; Classes of Fits	6.1
Applied Geometry	5.8	Accuracy of Drilled Holes	6.1
Orthographic Projection	5.8	Classes of Fit	6.1
		Common System of Fits and Clearances	6.2
		British Standards BS 4500 System	6.2
		BS 4500 Definitions:	6.2

TABLE OF CONTENTS

BS 4500 Basic Hole System.....	6.3	Twisting Wires.....	7.10
BS 4500 Basic Shaft System.....	6.3	Spliced Connections In Wire Bundles.....	7.10
Basic Hole Method - Metric.....	6.3	Lacing and Tying Wire Bundles.....	7.10
Dimensions, Allowances and Tolerances.....	6.3	Bend Radii.....	7.11
Dimensions.....	6.3	Wire Protection.....	7.11
Allowances.....	6.3	Protection Against Chafing.....	7.11
Tolerances.....	6.4	Protection Against High Temperature.....	7.11
Unilateral and Bilateral Tolerances.....	6.4	Protection Against Solvents and Fluids.....	7.12
Schedule of Fits and Clearances.....	6.4	Protection of Wires in Wheel Well Areas.....	7.13
Limits for Bow, Twist and Wear.....	6.4	Clamp Installation.....	7.13
Limits for Bow.....	6.4	Wire and Cable Clamp Inspection.....	7.14
Limits for Twist.....	6.4	Movable Controls Wiring Precautions.....	7.14
Limits for Wear.....	6.5	Conduit.....	7.14
Limits for Ovality.....	6.5	Heat Shrink Wrapping.....	7.14
Standard Methods for Checking Shafts, Bearings, and		Wire Shielding.....	7.15
Other Parts.....	6.5	Junction Boxes.....	7.16
Checking for Bow.....	6.5	High-Intensity Radiated Fields (HIRF) Protection Principles.....	7.16
Clearance Measured By Feeler Gauges.....	6.5	HIRF Protection.....	7.16
Checking for Twist.....	6.5	Soldering Electrical Wires.....	7.17
Piston Engine Connecting Rod Twist.....	6.5	Soldering Wires to a Circuit Board.....	7.17
Checking for Ovality.....	6.6	Soldering Wires to a Connector.....	7.18
Submodule 6 Practice Questions.....	6.7	EWIS Installation, Repair, Maintenance and Cleanliness.....	7.18
Submodule 6 Practice Answers.....	6.8	EWIS Standards.....	7.18
		EWIS Inspection, Repair and Maintenance.....	7.19
		EWIS Cleaning Requirements and Methods.....	7.20
		Submodule 7 Practice Questions.....	7.21
		Submodule 7 Practice Answers.....	7.22
7.7 - ELECTRICAL WIRING INTERCONNECT SYSTEM (EWIS).....	7.1		
Continuity, Insulation, Bonding, and Testing.....	7.1	7.8 - RIVETS.....	8.1
Continuity.....	7.1	Riveted Joints, Rivet Spacing, and Pitch.....	8.1
Insulation.....	7.1	Solid Shank Rivets.....	8.1
Bonding and Grounding.....	7.2	Rivet Head Shape.....	8.1
Grounding.....	7.2	Rivet Construction.....	8.1
Bonding.....	7.3	Solid Rivet Types.....	8.1
Testing of Bonds and Grounds.....	7.3	Repair Layout.....	8.2
Bonding Jumper Installation.....	7.3	Rivet Spacing.....	8.3
Stripping and Crimping Tools; Hand and Hydraulic.....	7.3	Edge Distance.....	8.3
Stripping Wire.....	7.3	Rivet Pitch.....	8.3
Terminal Strips.....	7.4	Transverse Pitch.....	8.3
Pre-Insulated Splices.....	7.4	Hand Tools.....	8.3
Crimping Tools.....	7.4	Rivet Cutter.....	8.3
Inspection and Testing of Crimped Joints.....	7.5	Bucking Bar.....	8.4
Connector Pin Removal and Insertion.....	7.5	Hand Rivet Set.....	8.4
Insertion.....	7.6	Dimple Dies.....	8.4
Removal.....	7.6	Chip Chasers.....	8.4
Adjacent Locations.....	7.6	Powered Tools.....	8.4
Sealing.....	7.6	Pneumatic Rivet Gun.....	8.4
Drainage.....	7.6	Rivet Sets and Headers.....	8.6
Coaxial Cables; Testing and Installation.....	7.7	Microshavers.....	8.6
Testing Coaxial Cable.....	7.8	Compression Riveting.....	8.6
Identification of Wire Types, Inspection and Damage Tolerance.....	7.8	Reusable Sheet Metal Fasteners.....	8.6
Identification of Wire Types.....	7.8	Cleco Fasteners.....	8.7
Placement of Identification Markings.....	7.8	Hex Nut and Wing Nut Fasteners.....	8.7
Types of Wire Markings.....	7.9	Riveting Procedures.....	8.7
Wire Inspection.....	7.9	Universal Head Rivets.....	8.7
Wire Protection: Cable Looms and Support, Clamps, Heat Shrink		Hole Transfer.....	8.7
Wrap and Shielding.....	7.9		
Wire Bundles and Routing.....	7.9		
Slack in Wire Bundles.....	7.10		

TABLE OF CONTENTS

Hole Preparation	8.7	7.11 - BEARINGS	11.1
Drilling	8.7	Testing, Cleaning, and Inspection of Bearings	11.1
Countersunk Rivets	8.8	Testing Bearings	11.1
Countersink Tools	8.8	Cleaning the Wheel Bearings	11.1
Dimpling	8.9	Wheel Bearing Inspection	11.1
Hot Dimpling	8.9	Lubrication Requirements of Bearings	11.3
Dimpling Inspection	8.10	Bearing Handling and Lubrication	11.3
Blind Rivets	8.10	Lubricants	11.3
Friction-Locked Blind Rivets	8.10	Storage	11.3
Mechanical-Lock Blind Rivets	8.11	Defects in Bearings and Their Causes	11.3
Removal of Mechanically-Locked Blind Rivets	8.12	Contamination and Corrosion	11.3
Inspection of Riveted Joints	8.12	Submodule 11 Practice Questions	11.5
Removal of SOLID Rivets	8.12	Submodule 11 Practice Answers	11.6
Replacing Rivets	8.13		
Submodule 8 Practice Questions	8.15	7.12 - TRANSMISSIONS	12.1
Submodule 8 Practice Answers	8.16	Inspection of Gears, Backlash	12.1
		Gears	12.1
7.9 - PIPES AND HOSES	9.1	Lash and Pattern	12.1
Metal Tubes and Pipes	9.1	Inspection of Belts and Pulleys, Chains and Sprockets	12.2
Bending and Belling/Flaring Aircraft Pipes	9.1	Belts and Pulleys	12.2
Tubing Sizes	9.1	Chains and Sprockets	12.2
Tube Cutting	9.1	Inspection of Screw Jacks, Lever Devices, and Push-Pull Rod Systems	12.3
Tube Bending	9.2	Jack Screws	12.3
Alternative Bending Methods	9.2	Levers	12.3
Tube Flaring	9.3	Push-pull Rod Systems	12.3
Rolling Type Flaring Tools	9.4	Submodule 12 Practice Questions	12.5
Double Flaring	9.4	Submodule 12 Practice Answers	12.6
Beading	9.4		
Flexible Hoses	9.6	7.13 - CONTROL CABLES	13.1
Flexible hose Size Designations	9.6	Swaging of End Fittings	13.1
Fabrication and Replacement of Flexible Hoses	9.6	Splicing	13.3
Inspection and Testing of Pipes and Hoses	9.6	Swaged Ball Terminals	13.3
Rigid Tubing Inspection	9.6	Cable Slippage In Terminal	13.3
Flexible Hose Inspection	9.6	Nicopress® Swaged End Fittings	13.3
Flexible Hose Testing	9.6	Inspection and Testing of Cables	13.4
Installation of Pipes and Hoses	9.7	Manufacturer Wire Splices	13.6
Rigid Tube Installation and Inspection	9.7	Testing Cable Tension	13.6
Connection and Torque	9.7	Aircraft Flexible Control Systems	13.6
Flareless Tube Installation	9.7	Cable System Installation	13.6
Hose Clamps	9.8	Cable Guides	13.6
Installation of Flexible Hose Assemblies	9.10	Bowden Cable Systems	13.7
Submodule 9 Practice Questions	9.11	Teleflex Cable Systems	13.7
Submodule 9 Practice Answers	9.12	Submodule 13 Practice Questions	13.9
		Submodule 13 Practice Answers	13.10
7.10 - SPRINGS	10.1	7.14.3 - ADDITIVE MANUFACTURING	14.1
Inspection and Testing of Springs	10.1	Common Additive Manufacturing Techniques	14.1
Visual Inspection	10.1	Additive Manufacturing Techniques	14.1
Static Measurment	10.1	Methods of Additive Manufacturing	14.1
Corrosion	10.1	Vat Photopolymerization	14.1
Overheating	10.2	Binder Jetting	14.1
Fatigue	10.2	Material Extrusion	14.2
Load Deflection	10.2	Ultrasonic Additive Manufacturing	14.2
Squareness Inspection of Valve Springs	10.2	Powder Bed Fusion	14.2
Submodule 10 Practice Questions	10.3	Directed Energy Deposition	14.2
Submodule 10 Practice Answers	10.4		

TABLE OF CONTENTS

Finishing Parts after Printing	14.2	Grounding and Bonding	17.15
Mechanical Properties of Finished Parts	14.2	Fueling Procedures	17.15
Inspection of Additive Manufactured Parts and Common		Over the Wing Refueling	17.15
Production Failures	14.3	Pressure Refueling	17.15
Common Production Failures	14.3	Defueling	17.17
Inspection of Additive Manufactured Parts	14.3	De-icing/Anti-Icing Procedures	17.17
Ultrasonic Testing	14.3	De-icing and Anti-icing of Transport Aircraft	17.17
Radiographic Testing	14.3	Deicing Fluid	17.17
CT Scans	14.3	Holdover Time (HOT)	17.17
Eddy Current Testing	14.3	Critical Surfaces	17.17
7.15 - RESERVED.....	15.1	Frost Removal	17.19
This submodule is reserved by EASA for future use.	15.1	Ice and Snow Removal	17.19
7.16 - AIRCRAFT WEIGHT AND BALANCE.....	16.1	Electrical, Hydraulic and Pneumatic Ground Supplies	17.19
This submodule is not required for Cat-A certification.	16.1	Electric Ground Power Units	17.19
7.17 - AIRCRAFT HANDLING AND STORAGE.....	17.1	Hydraulic Ground Power Units	17.20
Aircraft Taxiing/Towing and Associated Safety Precautions. .	17.1	Ground Support Air Units	17.20
Engine Starting and Operations	17.1	Ground Air Heating and Air Conditioning	17.20
Reciprocating Engines	17.1	Oxygen Servicing Equipment	17.20
Hand Cranking Engines	17.2	Oxygen Hazards	17.21
Turboprop Engines	17.3	Air/Nitrogen, Oil, and Fluid Servicing	17.21
Turboprop Starting Procedures	17.3	Effects of Environmental Conditions on Aircraft Handling and	
Turbofan Engines	17.4	Operation	17.21
Starting a Turbofan Engine	17.4	Submodule 17 Practice Questions	17.23
Auxiliary Power Units (APUs)	17.6	Submodule 17 Practice Answers	17.24
Unsatisfactory Turbine Engine Starts	17.6	7.18 - DISASSEMBLY, INSPECTION, REPAIR, AND	
Hot Start	17.6	ASSEMBLY TECHNIQUES	18.1
False or Hung Starts	17.6	Introduction	18.1
Engine Will Not Start	17.6	Section A	18.1
Extinguishing Engine Fires	17.6	Types of Defects and Visual Inspection	18.1
Taxiing Aircraft	17.6	Basic Inspection Techniques and Practices	18.1
Taxi Signals	17.7	Preparation	18.1
Towing Aircraft	17.7	Aircraft Logs	18.2
Aircraft Jacking, Chocking, Securing, and Associated		Checklists	18.2
Safety Precautions	17.10	Publications	18.2
Aircraft Jacking	17.10	Manufacturers' Service Bulletins and Instructions	18.2
Tiedown, Chocking and Securing	17.11	Maintenance Manuals	18.2
Securing Light Aircraft	17.11	Overhaul Manual	18.2
Securing Heavy Aircraft	17.11	Structural Repair Manual	18.2
Tiedown Procedures for Seaplanes	17.12	Illustrated Parts Catalog	18.2
Tiedown Procedures for Skiplanes	17.12	Visual Inspection Techniques	18.2
Tiedown Procedures for Helicopters	17.13	Types of Defects	18.2
Aircraft Storage Methods	17.13	External Damage	18.3
Hangars	17.13	Inlets and Exhausts	18.3
Fire Precautions	17.13	Liquid Systems	18.3
Storage Processes	17.14	Gaseous Systems	18.3
Phase 1 – Preparation	17.14	Landing Gear	18.3
Phase 2 – Routine Servicing	17.14	System Indicators and Gauges	18.3
Phase 3 – Repreparation In Storage	17.14	Probes	18.3
Phase 4 – Return To Service	17.14	Handles, Latches, Panels and Doors	18.4
Refueling/Defueling Procedures	17.14	Other Inspection Items	18.4
Fuel Types and Identification	17.14	Life Limited Items	18.4
Contamination Control	17.14	Corrosion Removal, Assessment and Reprotection	18.5
Fueling Hazards	17.15	Preventive Maintenance	18.5
		Corrosion Removal	18.5
		Surface Cleaning and Paint Removal	18.5

TABLE OF CONTENTS

Corrosion of Ferrous Metals	18.5	Submodule 19 Practice Questions	19.7
Mechanical Removal of Iron Rust	18.6	Submodule 19 Practice Answers	19.8
Chemical Removal of Rust	18.6		
Removal of Corrosion from Highly Stressed Steel Parts	18.6	7.20 - MAINTENANCE PROCEDURES	20.1
Corrosion of Aluminum and Aluminum Alloys	18.6	Maintenance Planning	20.1
Treatment of Unpainted Aluminum Surfaces	18.7	Modification Procedures	20.1
Treatment of Anodized Surfaces	18.7	Stores Procedures	20.2
Corrosion of Magnesium Alloys	18.8	Certification and Release Procedures	20.3
Treatment of Wrought Magnesium Sheet and Forgings	18.8	Interface with Aircraft Operation	20.3
Treatment of Installed Magnesium Castings	18.8	Maintenance Inspection/Quality Control/Quality Assurance	20.3
Protection of Dissimilar Metal Contacts	18.8	Additional Maintenance Procedures	20.3
Contacts Not Involving Magnesium	18.9	Control of Life-limited Components	20.4
Contacts Involving Magnesium	18.9	Submodule 20 Practice Questions	20.5
Corrosion Limits	18.9	Submodule 20 Practice Answers	20.6
Surface Preparation	18.9		
Chemical Treatments	18.9	7.21 - DOCUMENTATION AND COMMUNICATION	21.1
Anodizing	18.9	Documentation	21.1
Alodizing	18.10	Task Cards	21.1
Chemical Surface Treatment and Inhibitors	18.10	Work Reports / Technical Records	21.1
Chromic Acid Inhibitor	18.10	Personal Logbooks	21.1
Sodium Dichromate Solution	18.10	Troubleshooting Reports	21.2
Protective Paint Finishes	18.10	Shift Handover Instructions	21.2
Section B	18.10	The Handover Procedure	21.2
Disassembly and ReAssembly Techniques	18.10	Communication	21.3
Replacement of Major Components and Modules	18.11	Listening	21.3
Disassembly and Reassembly of Major Components	18.11	Asking Questions	21.3
Disassembly and Reassembly of Minor Components	18.11	Written Communication	21.3
Basic Disassembly and Reassembly Techniques	18.11	Basic Elements of Communication	21.3
Discarding of Parts	18.12	The Receiver	21.3
Freeing Seized Components	18.12	Effective Communication	21.3
Assembly	18.12	Clarity	21.3
Submodule 18 Practice Questions	18.13	Comprehensive	21.3
Submodule 18 Practice Answers	18.14	Concise	21.4
		Barriers to Effective Communication	21.4
7.19 - ABNORMAL EVENTS	19.1	Lack of Common Experience	21.4
Special Inspections	19.1	Lack of Precision	21.4
Inspection following Lightning Strikes and HIRF		Interference	21.4
Penetration	19.1	Writing Reports and Essays	21.4
Lightning Strikes	19.1	How to Write an Essay Answer	21.4
High Intensity Radiated Fields (HIRF) Penetration	19.2	Study the Question	21.4
Specific Testing - HIRF	19.2	Planning	21.4
HIRF Test Equipment	19.3	Writing the Essay	21.4
Signal Pulse Generators	19.3	Hints and Tips	21.5
Pulse Amplifiers	19.3	Submodule 21 Practice Questions	21.7
RF Power Meters	19.3	Submodule 21 Practice Answers	21.8
EMC Antennas	19.3		
Inspection Following Heavy Landings or Flight Through		Acronym Definitions	A.1
Turbulence	19.3		
Hard or Overweight Landings	19.3		
Post Heavy Landing Inspection	19.3		
Severe Turbulence Inspection	19.4		
Other Types of Damage	19.4		
Fire Damage	19.4		
Flood Damage	19.5		
Seaplanes	19.5		
Aerial Application Aircraft	19.5		

AIRPLANE DAMAGE CONSIDERATIONS

Personnel performing fuel tank work may damage the airplane if they are not trained to avoid such damage. The mating surfaces of the access hole and covers should be protected during entry so that the surfaces are not scratched or otherwise damaged. Components inside the tanks, such as fuel pumps, quantity systems and associated wiring and conduits are also vulnerable if they are struck or dislodged. Finally, the containment properties of the fuel tank can be compromised if the sealant is dislodged or if fuel tank bladders are penetrated.

BALLISTIC RECOVERY SYSTEMS

AWARENESS AND PRECAUTIONS REGARDING BALLISTIC RECOVERY SYSTEMS

BASIC UNDERSTANDING

Once the domain of microlights and small homebuilt aircraft, ballistic recovery systems can now be found on many general aviation aircraft including Cessna, Cirrus and even some light jets. These systems are designed as a last resort in the event of a collision, structural failure or engine failure over inhospitable terrain. While these events are extremely rare, the principle manufacturer claims over 380 "saves" to date, and many light aircraft manufacturer's now offer this option to ease the fears of buyers. Therefore, it not be uncommon for a light aircraft AMT to come across these systems in their daily work. [Figure 1-7]

PRIMARY COMPONENTS

Most ballistic recovery systems are rocket fired where a small solid fueled rocket type device pulls the parachute from its container stored inside the aircraft. However, some older systems operate more like a mortar where an explosive charge pushes the tightly packed canopy from a tube. In either case, the principle components of all systems include the parachute itself (canopy, suspension lines and risers), a pyrotechnic device and its igniter, an in-cockpit actuation handle, and the various structural components to house these parts and attach them to the aircraft.

In the event of an emergency, the system is activated by the pilot via an actuation handle in the cockpit. [Figure 1-8] The handle activates a rocket motor which extracts a harness and the packed



Figure 1-8. An actuation handle with its remove-before-flight safety pin in place.

canopy from its container located inside the aircraft. Once the canopy is extended it unfurls and lowers the aircraft at a survivable rate.[Figure 1-9]

SAFETY AROUND BALLISTIC RECOVERY SYSTEMS

The primary safety concern when working with or near ballistic systems is the unintentional firing of the rocket itself. Being struck by this device exiting the aircraft can be fatal. Never position yourself or allow others in the potential path of the rocket device. When handling a device that is not installed on the aircraft be aware of where the rocket is pointed at all times. Treat the device like a loaded gun. Even with the safety flag installed in the activation handle, know that a potential for an unintentional firing still exists, particularly if the device has been subjected to shock or high Gs. Mishandling or attempting to modify the igniter, rocket or any other component of a ballistic system can also cause an unintentional firing.

INSPECTION AND MAINTENANCE

Preflight and other inspections of ballistic parachute systems are primarily for a system's cleanliness, contamination, corrosion and other damage, and for the proper and secure attachment of all components; particularly the actuation handle, bridals and other attach points to the airframe. The parachute container must be



Figure 1-7. A ballistic parachute recovery of a Cirrus SR22.



Figure 1-9. The firing sequence of a rocket propelled parachute system.



Figure 3-44. Rotary punch press.



Figure 3-45. Foot-operated squaring shear.



Figure 3-46. Power squaring shear.

When cutting to a line, place the sheet on the bed of the shears in front of the cutting blade with the cutting line even with the cutting edge of the bed. To cut the sheet with a foot shear, step on the treadle while holding the sheet securely in place.

Squaring requires several steps. First, one end of the sheet is squared with an edge (the squaring fence is usually used on the edge). Then, the remaining edges are squared by holding one squared end of the sheet against the squaring fence and making the cut, one edge at a time, until all edges have been squared.

When several pieces must be cut to the same dimensions, use the backstop, located on the back of the cutting edge on most squaring shears. The supporting rods are graduated in fractions of an inch and the gauge bar may be set at any point on the rods.

Set the gauge bar the desired distance from the cutting blade of the shears and push each piece to be cut against the gauge bar. All the pieces can then be cut to the same dimensions without measuring and marking each one separately.

SANDERS

DISK SANDER

Disk sanders have a powered abrasive-covered disk or belt and are used for smoothing or polishing surfaces. The sander unit uses abrasive paper of different grits to trim metal parts. [Figure 3-47]

It is much quicker to use a disk sander than to file a part to the correct dimension. The combination disk and belt sander has a vertical belt sander coupled with a disk sander and is often used in a metal shop.

BELT SANDER

The belt sander uses an endless abrasive belt driven by an electric motor to sand down metal parts much like the disk sander unit. The abrasive paper used on the belt comes in different degrees of grit or coarseness. The belt sander is available as a vertical or horizontal unit. The tension and tracking of the abrasive belt can be adjusted so the belt remains centered on its rollers. [Figure 3-48]

GRINDERS

Grinding machines come in a variety of types and sizes, depending upon the class of work for which they are to be used. Dry and/or wet grinders are found in airframe repair shops. Grinders can be



Figure 3-47. Disk Sander.



Figure 3-48. Belt sander.




Figure 3-112. Saw-tooth applied voltage.

When the saw-tooth reaches the end of its sweep from left to right, the beam then rapidly returns to the left side and is ready to make another sweep. During this time, the electron beam is stopped or blanked out and does not produce any kind of a trace. This period of time is called flyback.

VERTICAL DEFLECTION

If this same signal were applied to the vertical plates, it would also produce a vertical line by causing the beam to trace from the down position to the up position.

TRACING A SINE WAVE

Reproducing the sine wave on the oscilloscope combines both the vertical and horizontal deflection patterns. [Figure 3-113] If the sine wave voltage signal is applied across the vertical deflection plates, the result will be the vertical beam oscillation up and down on the screen. The amount that the beam moves above the centerline will depend on the peak value of the voltage. While the beam is being swept from the left to the right by the horizontal plates, the sine wave voltage is being applied to the vertical plates, causing the form of the input signal to be traced out on the screen.

CONTROL FEATURES ON AN OSCILLOSCOPE

There are many different styles of oscilloscopes, which range from the simple to the complex, they all have some controls in common. Apart from the screen and the ON/OFF switch, some of these controls are listed next.




Figure 3-113. Sine wave voltage signal.

decimal form. When very accurate dimensions are necessary, decimal allowances are used. Fractional allowances are sufficient when precise tolerances are not required. Standard tolerances of -0.010 or $-\frac{1}{32}$ may be given in the title block of many drawings, to apply throughout the drawing.

FINISH MARKS

Finish marks are used to indicate the surface that must be machine finished. Such finished surfaces have a better appearance and allow a closer fit with adjoining parts. During the finishing process, the required limits and tolerances must be observed. Do not confuse machined finishes with those of paint, enamel, chromium plating, and similar coating.

SCALE

Some drawings are made the same size as the drawn part; reflecting a scale of 1:1. Other scales may be used. However, when drawings are made on a computer, drawing sizes may be easily increased (zoom in) or decreased (zoom out). Some electronic printers have the same capability. Furthermore, when a 1:1 copy of a print is made, the copy size may differ slightly from that of the original. For accurate information, refer to the dimensions shown on the drawing. [Figure 5-3H]

METHODS OF ILLUSTRATION

APPLIED GEOMETRY

Geometry is the branch of mathematics that deals with lines, angles, figures, and certain assumed properties in space. Applied

geometry, as used in drawings, makes use of these properties to accurately and correctly represent objects graphically. In the past, draftsmen utilized a variety of instruments with various scales, shapes, and curves to make their drawings. Today, computer software graphics programs show drawings at nearly any scale, shape, and curve imaginable, outdating the need for additional instruments. Several different methods are used to illustrate objects graphically. The most common are orthographic projections, pictorial drawings, diagrams, and flowcharts.

ORTHOGRAPHIC PROJECTION

To show the exact size and shape of all the parts of complex objects, several views are necessary. This is the system used in orthographic projection.

In orthographic projection, there are six possible views of an object, because all objects have six sides—front, top, bottom, rear, right side, and left side. **Figure 5-10A** shows an object placed in a transparent box, hinged at the edges. The projections on the sides of the box are the views as seen looking straight at the object through each side. If the outlines of the object are drawn on each surface of the box, and the box is then opened [Figure 5-10B] to lay flat [Figure 5-10C], the result is a six-view orthographic projection.

It is seldom necessary to show all six views to portray an object clearly; therefore, only those views necessary to illustrate the required characteristics of the object are drawn. One, two, and three-view drawings are the most common. Regardless of the number of views used, the arrangement is generally as shown in




Figure 5-10. Orthographic projection.




Figure 5-28. Example of an installation diagram (flight guidance components).