

PART #	MAKE/TCH	MODEL/SERIES
<b>CD31206 (Spark Plug Assembly)</b>		
G02C12	Beechcraft Corporation	65-90, 65-A90, B90, 99, 99A
<b>CD31207 (Spark Plug Assembly)</b>		
H02C12	Beechcraft Corporation	65-80, 65-A80, 65-B80, 65-88 A-65-8200, 70
<b>CD31111 (Spark Plug Assembly)</b>		
54A35	Beechcraft Corporation	B50, 95-B55 S/N TC-1608 thru TC-1657, E55, S/N TE-938, TE-943 thru TE-958, TE-960 thru TE-967, 56TC, A56TC, 58, S/N TH-1 thru TH-436, 95, B95, B95A, E95, E18S
<b>CD22030 (Spark Plug)</b>		
10D22, 756180	Piper Aircraft, Inc. Textron Aviation Inc. (Cessna)	PA-23, S/N PA-27-3050 and up, PA-23-250, S/N PA-27-3050, PA-27-3154 and up, PA-30, S/N 30-402 and up, PA-31, PA-39 310G, 310H, E310H, 310I, 310J, E310J, 310K, 310L, 310N, 310P, S/N 310P-0453, 320C, 320D, 320E, 320F, 337, 337A
<b>RA-D02C12 (Spark Plug)</b>		
D02C12	Twin Commander Aircraft LLC	500, 500-A, 500-B, S/N 0001 thru 0230
<b>CD22040 (Spark Plug)</b>		
10E75-3, 10D22, 39D18	Aerostar Aircraft Corporation Beechcraft Corporation Bell Helicopter Textron Canada Limited B-N Group Ltd. Emerald Enterprises LTD. (Wing) Piper Aircraft, Inc. Textron Aviation Inc. (Cessna) Twin Commander Aircraft LLC	PA-60-600, PA-60-601, PA-60-601P, PA-60-602P, PA-60-700P 58, S/N TH-0437 and up, 58P, 60, A60, B60, S/N P-0247 and up, 76, 95-B55, S/N TC-1658 and up, E55, S/N TE-0959, TE-0968 and up 206A, 206B, 206L BN-2, BN-2A, BN-2A-6, BN-2A-8, BN-2T D-1 PA-23, S/N PA-27-3050 and up, PA-30, S/N 30-402 and up, PA-31, PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-31-300, PA-31-325, PA-31-350, PA-34-200, PA-34-200T, PA-34-220T, PA-39, PA-44-180, PA-44-180T 208, 208B, T303, 310G, 310H, E310H, 310I, 310J, E310J, 310K, 310L, 310N, 310P, S/N 310P-0453, 320C, 320D, 320E, 320F, 500-S
<b>RA-54A35 (Spark, Plug)</b>		
54A35	Beechcraft Corporation	56TC, S/N TG-01 thru TG-83, A56TC, S/N TG-84 thru TG-94, 58, S/N TH-1 thru TH-436, 95-55, 95-A55, B50, C50, S/N CH-0012 thru CH-0360, D50, D50A, D50B, D50C, E50, F50, G50, H50, D50C, H50, S/N GH-0135 and up, J50, S/N JH-0150 thru JH-0176, E18S, G18S.
<b>CD39D18 (Spark Plug)</b>		
39D18	Aerostar Aircraft Corporation Beechcraft Corporation Bell Helicopter Textron Canada Limited Piper Aircraft, Inc. Textron Aviation Inc. (Cessna) Emerald Enterprises LTD. (Wing)	PA-60-600, S/N 0561 and up, PA-60-601, PA-60-601P 58, S/N TH-0437 and up, B60, S/N P-0247 and up, 76, 95-B55, S/N TC-1658 and up, E55, S/N TE-0959, TE-0968 and up 206A, 206B PA-23, S/N 27-7405428, 27-7554039 thru 27-8054059, 27-8154001 and up, PA-31, S/N 31-7401249, 31-7512065 thru 31-8012000, PA-31T, S/N 31T-7400002 thru 31T-7720069, PA-31T1, S/N 31T-7820001 thru 31T-7820066, S/N 34-7670001 and up, PA-44-180, PA-44-180T 414, 414A, S/N 414-0901 and up, 421C, S/N 421C-0201 and up D-1