

GASKETS



RAPCO REPLACEMENT EXHAUST GASKETS

High quality, economical stainless and copper beaded gaskets. Extra thick spiral wound style available "Blow Proof"

	Style	RAPCO P/N	Use As Replacement For:			Use on These Engine Models	Part No.	Price Each
			OEM P/N	Airborne P/N	Superior P/N			
CONTINENTAL	Solid 	RA630365	630365	N/A	SA630365	IO-360-A, C, D, G, H, J, K	08-05215	---
	Spiral Wound 	RA970	N/A	970	N/A	IO-360-A, C, D, G, H, J, K TSIO-360-A, B	08-05270	---
	Solid 	RA632837	632837 21493	157	SA 632837	A-65, A-75, C-85-12F, C-90-8F, 12F, 14F, -16F, E-165, E-185, E-225, O-200-A, B, O-300-A, C, D, O-470-A, E, J	08-05237	---
	Spiral Wound 	RA627429	627429	999	SA 627429	E-165, E-185, E-225 O-200-A, B, O-300-A, C, DO-470-A, E, J	08-05229	---
	Spiral Wound 	RA628260	628260	972	SA628260	O-470-B, G, K, L, M, P, R, S, U, IO-470-D, U, V, TSIO-470-B TSIO-520-B, C, D GTSIO-520-C, D	08-05260	---
LYCOMING	Solid 	RA75118	75118 73720 67196 77611	160	N/A	0-290, 0-320, IO-320, 0-340, 0-360, HO-260-B, IO-360-A, -B, -C, HIO-360-A, -B, -C, V0-435, TVO-435, G0-480, GSO-480, ISGO-480, O-540-A, -B, -E, -G, IO-540-A, -C, -D, -G, -J, -K, IGO-540-A, IGS0-540-A, 10-720-A	08-05218	---
	Spiral Wound 	RA77611	77611	1000	SL77611		08-05211	---
	Spiral Wound 	RALW15486	LW15486	971	N/A		08-05286	---
	Solid 	RA985	3503			R-985-AN-1, -3, -4, -6, -6B, -10, 12, -12B, -14B	08-64452	---

EP

REPLACEMENT GASKET FOR WOODWARD GOVERNORS

Part Name	Approved Replacement for Part No.	Model Eligibility	Part No.	Price
 Propeller Governor Gasket	Woodward Gov. 206684 Pratt & Whitney 3039526	PT6A-20/20A/-20B/-21/-25C/-27/-28/-34/-34AG/-34B/-36/-38/-41/-42/-42A/-60A/-60AG/-61/-67A/-67AF/-67AG/-67B/-67D/-67R/-67T/PT6A-45A/-45B/-45R/-65B/-65AG/-65AR/-65R/-114/-114A/-135/-135A	08-06264	---
 Propeller Governor Gasket	Woodward Gov. 206685 Pratt & Whitney 3118953-01	PT6A-6/-6A/-6B/-11/-11AG/-15AG/-20/-20A/-20B/-34/-34AG/-34B/-36/-38/-41/-42/-42A/-45/-45A/-45B/-45R/-60A/-60AG/-61/-65B/-65R/-67/-67A/-67AF/-67AG/-67B/-67D/-67R/-67T/-110/-112/-121	08-07154	---

2577256 PRECISION AIRMOTIVE GASKET PEX-1

Gasket part number 365533 is no longer available from Precision Airmotive. The new gasket, part number 2577258 is available and should be used in place of 365533.

P/N 07-01312 ---

TCM VACUUM PUMP GASKET 653487

TCM vacuum pump gasket 653487. This is for the Continental 0200 and the 0470.

P/N 08-00297 ---

SILICONE VALVE COVER GASKETS

These reinforced silicone with fiberglass valve cover gaskets are (.093) 3/32. The torque needed is 25/27 inch pounds. Won't sponge or tear & come with a lifetime warranty from the manufacturer.....P/N 05-11931 ---

THESE GASKETS ARE NOT FAA APPROVED.

LYCOMING ASSEMBLY DRIVE GASKET SL73818

Lycoming Assembly Drive Gasket SL73818. Replace-ment for Textron Lycoming P/N 73818.

P/N 08-00306 ---